Job Hazard Analysis
University of Delaware
Department of Occupational Health and Safety

Job Title_Coordinator (X-ray) Date_____
Task Evaluated_____ JHA#_____
Prepared By: Virginia Falgowski _ Reviewed by_Steve Grasson____

Approved by __Supervisor ___ Chairperson/Director
__Safety Chair ___Occupational Health & Safety

Job Description	Hazard Identification	Required Precautions
Moving x-ray arm, table, stand, and removing cassettes	Jerking motion may cause strain	Do not jerk; remove cassettes and move equipment without jerking.
Adding chemicals to processor	Splashing	Wear gloves and safety glasses
Moving patients	Back strain	Bend knees
Moving film cassette	Dropping cassettes	Wear proper footgear
Fumes from processor and darkroom	Smelling fumes	Check vents and assure proper preventive maintenance.
Taking radiation	Radiation exposure	Stand behind lead walls
Paperwork	Back and wrist strain	Proper lighting, ergonomics
Illness of patients	Exposure to disease	Isolation technique